



2 - THIRTY INCH VERI-FLEXIBLE 1/2"
FULL FLOW STAINLESS STEEL TUBES
4 - 1/2" MPT TO SWEAT COPPER ADAPTORS



SOLDER FITTINGS TO
TOASTER UNIT INLET &
OUTLET

SOLDER FITTINGS TO
STUB OUTS AT
CONNECTION
MAKE SURE DISTANCE
IS UNDER 28" TOTAL
USE MIN 1-1/8" PADDLE
BIT TO PASS TUBE
THRU STUD OR FLOOR

<http://www.turbonicsinc.com>
260 North Elm Street
Westfield, MA 01085 USA

EZ-2 K'NECT-KIT



AFTER SOLDERING
ALWAYS USE TWO
WRENCHES
TO TIGHTEN. KEEP THE
WRENCH ON SOLDER
JOINT "STILL "
AND AVOID TWISTING TO
INSURE LEAK PROOF
INSTALLATIONS



**** Innovation is an American Tradition ****

Phone (413) 568-9571 Fax (413) 568-9613